

BOLU TAŞINMAZ KÜLTÜR VE TABİAT VARLIKLARI ENVANTERİ**MUDURNU İLÇESİ - SİVİL MİMARİ YAPILAR**

ADI	Bökesoylar Konağı-Konut		
ENVANTER NO	51	KADASTRAL DURUMU	
İLİ	Bolu	PAFTA	30-27-Ad
İLÇESİ	Mudurnu	ADA	207
MAHALLESİ	Hızırfağı Mahallesi	PARSEL	10
TESCİL DURUMU	Ankara Kültür ve Tabiat Varlıklarını Koruma Kurulu'nun 16.10.1995 tarih ve 4219 sayılı kararı ile tescil edilmiştir.		

Bolu İli, Mudurnu İlçesi, Hızırfağı Mahallesi, Değirmen Sokak, 30-27-Ad pafta, 207 ada, 10 parselde yer alan yapı zemin + 2 katlıdır. Zemini taş yığma olan yapı, ahşap karkas arası dizeme üstü sıvalıdır. Değirmen Sokaktan çift kanatlı ahşap kapı ile girilir. Kapının üstünde boyunca uzanan ışıklığın üstü ahşap zikzak kafesle örtülüdür. Kapının sol yanında küçük bir servis penceresi vardır. 1. katta ahşap pencereli dikdörtgen pencereler bulunmaktadır. 2. katta sağ köşede ahşap merteklerin uzatılmasıyla yapılmış çıkma üzerinde basık kemerli ve ortada dilimli kemerli dikdörtgen pencereler vardır. 2. kattaki pencere altları dilimli ahşap süslemeler ile bezenmiştir. Sağ yan cephe 1. kattaki küçük servis penceresi hariç sağır bırakılmıştır. Sol yan cephede zemin sağırdır ve arka taraf yarıdan itibaren çıkma şeklinde düzenlenmiştir. Sadece ön cephe ve sağ taraftaki cephe sıvalıdır. Kat aralarında ahşap silme, köşelerde ahşap dikmeler yer alır.

Kırma çatı, alaturka kiremitle kaplıdır. Saçak altı kaplamasızdır.



Bökesoylar Konağı, Bolu Müze Müdürlüğü Arşivi

BOLU IMMOVABLE CULTURAL AND NATURAL HERITAGE INVENTORY**MUDURNU DISTRICT – CIVIL ARCHITECTURE DISTRICT**

NAME	Bökesoylar Mansion-Residence		
INVENTORY NO	51	CADASTRAL INFORMATION	
CITY	Bolu	SHEET	30-27-Ad
DISTRICT	Mudurnu	BLOCK	207
NEIGHBORHOOD	Hızırfağı Neighborhood	PLOT	10
REGISTRATION STATUS	It is registered by the 4219 numbered, 16.10.1995 dated decision of the Ankara Cultural and Natural Heritage Conservation board.		

The structure located on Sheet 30-27-Ad, Block 207, Plot 10, in Bolu city, Mudurnu district, Hızırfağı Neighborhood, Değirmen Street is a two-storey structure with a ground floor. The construction technique consists of plastered masonry infill between a wooden frame resting on a stone foundation. A skylight above the door features a zigzag-patterned wooden lattice. A service window is present to the left of the door. The first floor features wooden-framed rectangular windows, while the second floor has rectangular windows with segmental arches and a centrally lobed arch on the oriel. Windowsills on the second floor are decorated with lobed wooden ornaments. The right-side facade is a blank wall except for a small window on the first floor. The ground on the left side facade is a blank wall and rear side is constructed as a cantilevered projection starting from the middle onward. Only the front facade and the right facade are plastered. Timber tie beams are installed between the floors, and wooden posts are utilized at the corners.

The hipped roof is covered with Anatolian pantiles. The eaves soffit is left unclad.



Bökesoylar Mansion, Bolu Museum Directorate Archive