

BOLU TAŞINMAZ KÜLTÜR VE TABİAT VARLIKLARI ENVANTERİ**MUDURNU İLÇESİ - SİVİL MİMARİ YAPILAR**

ADI	Pamuklar Evi-Konut		
ENVANTER NO	7	KADASTRAL DURUMU	
İLİ	Bolu	PAFTA	26-30-Za
İLÇESİ	Mudurnu	ADA	126
MAHALLESİ	Kaygana Mahallesi	PARSEL	3
TESCİL DURUMU	Ankara Kültür ve Tabiat Varlıklarını Koruma Kurulu'nun 16.10.1995 tarih ve 4219 sayılı kararı ile tescil edilmiştir.		

Bolu İli, Mudurnu İlçesi, Kaygana Mahallesi, 26-30-Za pafta, 126 ada, 3 parselde yer alan zemin + 2 katlı yapı, bahçe içerisinde yer almaktadır. Yapı tekniği ahşap karkas arası dizme üstü sıvalıdır. Yapıya giriş merdivenlerle çıkılan 2 kapıdan sağlanmaktadır. Ön cephede 1. ve 2. kat boyunca yükselen çıkma, profilli ahşap konsollarla desteklenmiştir. Giriş cephesi üzerinde yapının sağ tarafında havalandırma pencereleri, sol tarafında giyotin tarzı dikdörtgen pencereler, çıkma üzerinde ise İspanyol tipi pencere bulunmaktadır. Sağ ve sol cepheler sağır bırakılmıştır. Arka cephede de giriş cephesinde olduğu gibi 1. ve 2. kat üzerinde, ortada ahşap konsollarla desteklenen çıkma yer almıştır. Zemin kat ve 1. katta İspanyol tipi pencere, 2. katta ise pencere denizliklerinin altı ahşap bezemeli giyotin tarzı dikdörtgen pencereler bulunmaktadır.

Kırma çatısı alaturka kiremitle örtülüdür ve geniş saçaklıdır.



Pamuklar Evi, Bolu Müze Müdürlüğü Arşivi

BOLU IMMOVABLE CULTURAL AND NATURAL HERITAGE INVENTORY			
MUDURNU DISTRICT – CIVIL ARCHITECTURE STRUCTURES			
NAME	Pamuklar House-Residence		
INVENTORY NO	7	CADASTRAL INFORMATION	
PROVINCE	Bolu	SHEET	26-30-Za
DISTRICT	Mudurnu	BLOCK	126
NEIGHBORHOOD	Kaygana Neighborhood	PLOT	3
REGISTRATION STATUS	It was registered by the Ankara Cultural and Natural Heritage Conservation Board with decision no. 4219 dated 16.10.1995.		
The two-fold building with a ground floor, located in Bolu Province, Mudurnu District, Kaygana Neighborhood, sheet 26-30-Za, Block 126, Plot 3, is situated in a garden. The construction technique consists of a wooden frame with infill, covered with plaster. Access to the building is provided through two doors reached by a set of stairs. On the front façade, a cantilevered projection extending across the first and second floors is supported by a wooden bracket (timber column). On the entrance façade, there are ventilation windows on the right side, guillotine-style rectangular windows on the left side, and a Spanish-style window on the corbel above. The right and left façades are blind. On the rear façade, like the front, there is a central corbel on the first and second floor supported by a wooden bracket (timber column). On the ground floor and first floor, there are Spanish-style windows, while on the second floor, there are rectangular guillotine-style windows with wooden ornamentation below the windowsill. The roof is hipped and covered with traditional Turkish pantiles.			
			
Pamuklar House, Bolu Museum Directorate Archive			
			